

## Section 5.4: Statistical Process Control


Tuesday, February 27, 2018 3:48 PM

idea: making identical objects on an assembly line

for quality control purposes, every now and again, choose  $n$  objects and measure  $x$ , same characteristic, for each object

assume  $x$  is a continuous variable

then calculate  $\bar{x}$  for the sample and plot as a function of time



UCL = upper control limit

LCL = lower control limit

so, what should the graph look like?

$\bar{x}$  should vary about the (unknown) population mean  $\mu$

and almost all  $\bar{x}$  will fall within

$$\mu \pm 3 \frac{SE}{\sqrt{n}}$$

standard error

$$\mu \pm 3 \frac{\sigma}{\sqrt{n}}$$

← note: we don't actually know  $\mu$ , but can estimate it over time from samples

how?

calculate  $\bar{\bar{x}}$  - the mean of the sample means

$s$  - standard deviation of all observations

then

upper control limit  $UCL = \bar{\bar{x}} + \frac{3s}{\sqrt{n}}$  ← <sup>ess</sup>

lower  $LCL = \bar{\bar{x}} - \frac{3s}{\sqrt{n}}$

so, put limits on chart, and if  $\bar{x}$  deviates out beyond these limits, there's likely a problem

---

sample proportion - same idea

---

example: A producer of brass rivets randomly samples 500 rivets every hour and calculates the proportion of defectives. The mean sample proportion calculated from 10 000 samples was 0.025

- Calculate the UCL and LCL limits for a control chart.
- What does it mean if the next ten samples are above the UCL line?

$$\begin{aligned} a) \quad \bar{p} \pm 3SE &= \bar{p} \pm 3 \sqrt{\frac{pq}{n}} \\ &= 0.025 \pm 3 \sqrt{\frac{(0.025)(0.975)}{500}} \\ &= 0.025 \pm 0.021 \end{aligned}$$

$$\text{so } UCL = 0.046$$

$$LCL = 0.004$$

- if 10 samples are above the UCL, this is statistically extremely unlikely to happen by chance - so there's likely a problem that you should look into